

---

Subject: OT: guitar amp noise

Posted by [uptown jimmy](#) on Thu, 01 Sep 2005 20:22:58 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

th the chip architecture. Which would be preferable if the operating frequency was equal?

Mr. Simplicity is getting antsy for more horses for the Cubase machine.

;o)I had some trouble with mine with one pair of SATA ports not working and had to send it back, which took two attempts, and the turnaround per attempt was ten days, so I've only just got a new one last week and gotten back on it.

That said, it seems a very nice board. One thing I have noticed is that BIOS versions after version 6 don't have nearly as much IRQ control. They

---