

---

Subject: Genelec 1031 control room lacks bass response ?

Posted by [Dimitrios](#) on Mon, 22 Jan 2007 19:36:15 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

one or more tracks to any bus and have that bus

>> routed to the HDS 16. My brain stops working when I get to the part where

>> the entire mix is sent to the HDS 16 stereo input bus.

>>

>> Basically, what I need to be able to do is to bus a mono track to a mono

>> input of the HDS 17 while that same mono track is assigned to a stereo us

>> which is being output to a stereo input of the HDS16 and then all stereo

---