

[View Forum Message](#) <> [Reply to Message](#)

href=3D"http://www.adkproaudio.com">

[View Forum Message](#) < > [Reply to Message](#)

<DIV>Tom </DIV></BODY></HTML>

-----= NextPart 000 0098 01C63B58.32452170--This is a multi-part m

[View Forum Message](#) <> [Reply to Message](#)

The PARIS Forums

off.

On Mon, 27 Feb 2006 06:32:23 -0500, "Tom Bruhl" <arpegio@comcast.net> wrote:

>Rick,

>As Mr. Davis (not Sammy) would say:

>"You're freakin' me out..."

>

>Two comps both connected via USB? Hubs are great huh?

>I'm spooked but it's good that you got that happening.

>

>I think the Motu Clockworks software is the problem

>at this end. Now that it's programmed I won't let it see

>the software. I know many are happy with Motu products.

>I am so disgusted with drivers, incompatibility and bugs

>that I am less patient than I used to be. Most hardware that

>is software driven (internally) is usually very stable if not

>missing a few features. I'd prefer stability anytime.

>T.

>

>

>

>

> "rick" <parnell68@hotmail.com> wrote in message
news:p4j502po6jf055k5ue2gv7fqhfbh5pj3kr@4ax.com...

> no, i'm using the 4x4 for the m24 controller (3 I/O's) and one for the

> keystation. actually it's connected to both the mac and a pc via usb

> to allow sharing of hardware.

>

> On Sun, 26 Feb 2006 17:02:13 -0500, "Tom
