
Subject: Transient Suppressor

Posted by [brandon\[2\]](#) on Mon, 14 May 2007 12:40:37 GMT

[View Forum Message](#) <> [Reply to Message](#)

gt;

> :D lolcool, thanks Carl, I'll try that. It seems to be better since I tried the grounding problem, but I'll give it more of a workout tomorrow to see if I get any more noise explosions.

michael

"Carl Amburn" <carlamburn@hotmail.com> wrote:

>This doesn't sound like a ground loop issue to me - could be some kind of
>clocking problem or software/hardware issue. You might check your EDS cable
>connections and might also try re-seating the card.

>

>-Carl

>

>"michael bliss" <mbliss1@austin.rr.com> wrote in message

>news:466c8815@linux...

>>

>> I'm getting blasts of short static sounds. On every project so it's

>something

>> in the set-up. I also was reading the Laptop noise thread and thought
this

>> is my problem too.

>>

>> If it is a ground loop, would it be electrical for the computer or the

pre

>> amps or various other outboard gear I'm using, or could it be any other

>problem?

>>

>> thanks,

>>

>> michael

>

>I'll ditto Carl's thoughts - sounds like clocking problems to me as well.

AA