

---

Subject: Cream

Posted by [DC](#) on Thu, 08 Dec 2005 21:43:07 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

lank">43bb1b28@linux...

>

>>You need 1 mec per submix, otherwise you have to swap them around for

>>recording. Also use Virtual submixes if you need to playback more

>>submixes than you have EDS cards.

>>

>>

>>Throw that MEC around. This is a REALLY QUICK way to throw your MEC and

>>Patchbay from submix to submix. With practice you can do it in less

>>than 10 seconds. Need 16 more

---